


# Weak Signal from Signaler to Receiver, Receiver not working:

The further away the less signal strength

Outlet with Signaler plugged in.  
Telephone / doorbell Signal is 100%  
in signal strength



**Receivers must have a min. of 20% signal strength**

SA101 / SA201 / RH100 / BL300

**Note:**

Surge protectors have noise filters that will weaken the signal strength.  
Power strips can have the same effect.  
GFI type outlets found in kitchens and bath rooms should not be used.  
Halogen type lighting can cause false signals.

